
Crowell & Moring LLP Customer Service No. 23911


Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 1 of 14

FIG. 1




Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 2 of 14






Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 3 of 14



Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 4 of 14









FIG. 5(b)



Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 6 of 14






FIG. 7 12 13 20B 41 <sup>23B</sup> 10 23A 11 24 49 44 46 20A Ν 45 S 47 22 Ν 50 40A 40B 48 42

Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 7 of 14

7 / 14









Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 8 of 14

8 / 14



Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 9 of 14





Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 10 of 14

FIG. 12





FIG. 13



Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 11 of 14





FIG. 14

Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 12 of 14

12 / 14





SURFACE MAGNET TYPE

BUILT-IN MAGNET TYPE

Attorney Docket No. 381NP/50960 Filed: February 27, 2002 Sheet 13 of 14




FIG. 16

